

STRUCTURAL EVALUATION OF
VISTA HILLS STAFF DEVELOPMENT CENTER
WEST CONTRA COSTA UNIFIED SCHOOL DISTRICT
(WCCUSD)

For

WLC Architects
Kaiser Building
1300 Potrero Avenue
Richmond, CA 94804

By

DASSE Design, Inc.
33 New Montgomery Street #850
San Francisco, CA 94105
(415) 243-8400

April 30, 2002

DASSE Design Project No. 01B300

TABLE OF CONTENTS

	Page No.
10.1 Introduction.....	1
10.2 Description of School	1
10.3 Site Seismicity	1
10.4 List of Documents.....	2
10.5 Site Visit.....	2
10.6 Review of Existing Drawings	2
10.7 Basis of Evaluation	3
10.8 List of Deficiencies.....	3
10.9 Recommendations.....	4
10.10 Portable Units.....	4
10.11 Structural Deficiency Prioritization	5
10.12 Conclusions.....	5
10.13 Limitations and Disclaimer.....	6

List of Figures

- Figure 1: School layout plan
- Figure 2: Front Entrance
- Figure 3: Front Entrance
- Figure 4: Courtyard
- Figure 5: Courtyard
- Figure 6: Portable Building
- Figure 7: Rear View
- Figure 8: Rear View
- Figure 9: Interior
- Figure 10: Glu-Lam Beam at Front

10.1 Introduction

The purpose of this report is to perform a seismic assessment of the Vista Hills Staff Development Center in Richmond, CA. The structural assessment includes a site walk through and a limited study of available architectural and structural drawings. The purpose of the structural assessment is to identify decay or weakening of existing structural materials (when visible), to identify seismic deficiencies based on our experience with school buildings, and to identify eminent structural life-safety hazards.

The school campus has had a walk-through site evaluation and a limited study of available architectural and structural drawings. The general structural condition of the buildings and any seismic deficiencies that are apparent during our site visit and review of existing drawings are documented in this report. This report includes a qualitative evaluation and, therefore, numerical seismic analysis of buildings is not included.

The site visits did not include any removal of finishes. Therefore, identification of structural conditions hidden by architectural finishes or existing grade was not performed.

10.2 Description of School

The facility was built in 1962 as a school and later converted to a staff development center. In 1980 part of the structure was restored as a result of fire damage. The facility consists of an administrative area and several classroom units. The building is a one-story wood and masonry structure. The total square footage of the permanent structures is about 10,177 square feet.

10.3 Site Seismicity

The site is a soil classification S_C in accordance with the 1998 California Building Code (CBC) and as per the consultants, Jensen Van Lieden Associates, Inc.

The main classroom building has an educational occupancy (Group E, Division 1 and 2 buildings) which has an importance factor in the 1998 CBC of 1.15. The campus is located at a distance of less than 2.0 kilometers from the Hayward fault. The main classroom building is a wood framed and masonry structure. The plywood and masonry shear walls have a response modification factor $R=4.5$. The 1998 CBC utilizes a code level earthquake, which approximates an earthquake with a 10% chance of exceedance in a 50-year period or an earthquake having a 475-year recurrence period.

The seismic design coefficient in the 1998 CBC is:

$$V = \frac{2.5CaIW}{R} = \frac{2.5(0.40 \times 1.5 \times 1.15)W}{4.5} = 0.383W$$

The site seismicity is used to provide a benchmark basis for the visual identification of deficient elements in the lateral force resisting systems of campus buildings.

10.4 List of Documents

1. Fire Damage Restoration Vista Hills Elementary School, dated Sept. 1980, by Barvachand and Associates Inc. Architects, Sheets X1, X2, A1-A10, S1-S7.
2. Vista Hills Elementary School Staff Development Center, dated Aug. 18, 1989, by Interactive Resources Inc., Architect, Sheets X1, X2, A1-A10, S1-S7.
3. "Measure M" – WCCUSD Elementary School – UBC revised parameters by Jensen-Van Lienden Associates, Inc., Berkeley, California.
4. "Geological Hazard Study – Recently constructed portable buildings – 24 school sites for Richmond Unified School District," by Jensen-Van Lienden Associates, Inc. dated March 7, 1990.
5. "Measure M" roofing report by "the Garland Company Inc.", Orinda, California.

10.5 Site Visit

DASSE visited the site on October 24th, 2001 and March 7th, 2002. The main purpose of the site visit was to evaluate the physical condition of the structure and in particular focus on the lateral force resisting elements of the building. Following items were evaluated during the site visit:

1. Type and Material of Construction
2. Type of Sheathing at Roof, Floor, and Walls
3. Type of Finishes
4. Type of Roof
5. Covered Walkways
6. Presence of Clerestory Windows
7. Presence of Window Walls or High Windows in exterior and interior walls
8. Visible cracks in superstructure, slab on grade and foundation

During the visit it was observed that the roof structure consisted of straight sheathing supported by Glu-lam beams. The exterior walls were either stucco over wood or CMU (Figures 4, 5, & 7).

At the inner corridor wall there are continuous windows over CMU walls (Figures 4, 5).

There were several tall CMU columns (Figures 3 & 10) near the campus entrance that had Glu-Laminated beams resting on them and no bracing or blocking between the bottom of the beams and the roof diaphragm.

At one of the roof beams that extend out on the North-West side there was some indication at the top of the beam of what could be decay.

10.6 Review of Existing Drawings

The structural drawings that were available were copies of the 1980 fire reconstruction drawings that incorporated the original structural drawings. Some of the text on the structural drawings is not very readable. In addition drawings for the 1989 conversion to a staff development center were available.

At some time between 1980 and 1989 the space between the administrative unit and the classroom building was enclosed.

The roof structural system consists of a layer of 3/8" thick plywood over 3x6 T&G wood decking that was supported by Glu-laminated beams at 11 feet o.c. which in turn are supported by either wood posts or masonry walls or columns. The foundation consists of continuous spread footings that are integrated into the concrete slab-on-grade that acts as a floor.

The lateral forces are resisted by the plywood over the 3x roof planks which acts as a diaphragm to transfer the loads to the plywood and masonry shear walls. Where the continuous windows occur over the CMU walls the out of plane forces are resisted by the CMU walls that cantilever from the foundation. The connection of the diaphragm to the CMU shear walls should be evaluated since it appears to be less than is typically provided in new construction.

The roofing report prepared for this project indicated that the roof was about 22 years old and thus re-roofing should occur. It should be noted that the 1989 drawings indicate that the existing roof was to be removed.

10.7 Basis of Evaluation

The document FEMA 310, Federal Emergency Management Agency, "*Handbook for the Seismic Evaluation of Buildings – A Prestandard,*" 1998, is the basis of our seismic evaluation methods, although no numerical structural analyses were performed. The seismic performance levels that the FEMA 310 document seeks to achieve are lower than the current Building Code. However, it attempts to identify potential for building collapse, partial collapses, or building element life safety falling hazards when buildings are subjected to major earthquake ground motion.

10.8 List of Deficiencies

Building deficiencies listed below have corresponding recommendations identified and listed in Section 10.9, which follow the same order as the itemized list of deficiencies identified below. The severity of the deficiency is identified by a "*structural deficiency hazard priority*" system based on a scale between 1.0 and 3.9, which is described in Section 10.11. These priority ratings are listed in section 10.9. Priority ratings between 1.0 to 1.9 could be the causes for building collapses, partial building collapses, or life-safety hazards, if the corresponding buildings are subjected to major earthquake ground motions, which are possible at these sites. It is strongly recommended that these life safety hazards are mitigated by implementing the recommendations listed below.

Item	Building Structural Deficiencies
------	----------------------------------

1.	Exterior walls where masonry does not extend to the roof have limited capacity to resist out of plane forces.
2.	Main Building entrance canopy has tall CMU pilasters which do not appear to be adequately anchored to the roof.
3.	Concern about the adequacy of the connection of roof drags and collectors to the masonry shear walls.
4.	Top of beam extending from the North-West wall appears to have some decay.

10.9 Recommendations

Items listed below follow the same order as the itemized list of deficiencies identified in section 10.8 above.

Item	Recommended Remediation	Priority	Figure Number
1.	Where the masonry walls do not extend to the roof, provide pilasters on face of wall extending from slab-on-grade to roof.	1.5	4, 5
2.	Provide additional lateral bracing between the top of the entry canopy CMU pilasters and the roof.	1.1	2, 3, 10
3.	Strengthen the anchorage of roof drags into the masonry shear walls.	1.9	N/A
4.	Eliminate cause of decay and repair damage.	3.5	N/A

10.10 Portable Units

In past earthquakes, the predominant damage displayed by portable buildings has been associated with the buildings moving off of their foundations and suffering damage as a result. The portables observed during our site visits tend to have the floor levels close to the ground, thus the damage resulting from buildings coming off of their foundation is expected to be minimal. The life safety risk of occupants would be posed from the potential of falling 3 feet to the existing grade levels during strong earthquake ground shaking. Falling hazards from tall cabinets or bookshelves could pose a greater life safety hazard than building movement. The foundation piers supporting the portable buildings tend to be short; thus the damage due to the supports punching up through the floor if the portable were to come off of its foundation is not expected to be excessive.

Because of their light frame wood construction and the fact that they were constructed to be transported, the portable classrooms are not in general expected to be life safety collapse hazards. In some cases the portables rest directly on the ground and though not anchored to the ground or a foundation system could only slide a small amount. In these instances the building could slide horizontally, but we do not expect excessive damage or life safety hazards posed by structural collapse of roofs.

The regulatory status of portables is not always clear given that portables constructed prior to 1982 will likely have not been reviewed by DSA and thus will likely not comply with the state regulations for school buildings. Portables constructed after about 1982 should have been permitted by DSA. The permits are either issued as temporary structures to be used for not more than 24 months or as permanent structures.

10.11 Structural Deficiency Prioritization

This report hazard rating system is based on a scale of 1.0 to 3.9 with 1.0 being the most severe and 3.9 being the least severe. Based on FEMA 310 requirements, building elements have been prioritized with a low rating of 1.0 to 1.9 if the elements of the building's seismic force resisting systems are woefully inadequate. Priority 1.0 to 1.9 elements could be the causes for building collapses, partial building collapses, or life-safety falling hazards if the buildings were subjected to major earthquake ground motion.

If elements of the building's seismic force resisting system seem to be inadequate based on visual observations and based on FEMA 310 requirements, but DASSE believes that these element deficiencies will not cause life-safety hazards, these building elements have been prioritized between a rating low of 2.0 to 3.9. These elements could experience and / or cause severe building damage if the buildings were subjected to major earthquake ground motion. The degree of structural damage experienced by buildings could cause them not to be fit for occupancy following a major seismic event or even not repairable.

The following criteria was used for establishing campus-phasing priority:

First, the individual element deficiencies which were identified during site visit and review of existing drawings were prioritized with a rating between 1.0 to 3.9 and as described in this section.

The next step was to arrive at a structural deficiency rating between 1 and 10, with a rating of 1 representing a school campus in which the building's seismic force resisting systems are woefully inadequate.

Based on the school district's budgetary constraints and scheduling requirements, each school campus was given a phasing number between one and three. Phase I represents a school campus with severe seismic deficiencies, Phase II represents a school campus with significant seismic deficiencies and Phase III represents a school campus with fewer seismic deficiencies.

10.12 Conclusions

1. Given the vintage of the building(s), some elements of the construction will not meet the provisions of the current building code. However, in our opinion, based on the qualitative evaluations, the building(s) will not pose serious life safety hazards if the seismic deficiencies identified in section 10.8 are corrected in accordance with the recommendations presented in section 10.9.

2. Any proposed expansion and renovation of the building should include the recommended seismic strengthening presented in section 10.9. Expansion and renovation schemes that include removal of any portion of the lateral force resisting system will require additional seismic strengthening at those locations. It is reasonable to assume that where new construction connects to the existing building, local seismic strengthening work in addition to that described above will be required. All new construction should be supported on new footings.
3. Overall, this school campus has a seismic priority of 8 and we recommend that seismic retrofit work be performed in Phase III.



10.13 Limitations and Disclaimer

This report includes a qualitative (visual) level of evaluation of each school building. Numerical seismic analyses of buildings are not included in this scope of work. The identification of structural element code deficiencies based on gravity and seismic analysis demand to capacity evaluations are therefore not included. Obvious gravity or seismic deficiencies that are identified visually during site visits or on available drawings are identified and documented in this report.

Users of this report must accept the fact that deficiencies may exist in the structure that were not observed in this evaluation. Our services have consisted of providing professional opinions, conclusions, and recommendations based on generally accepted structural engineering principles and practices.

DASSE's review of portable buildings has been limited to identifying clearly visible seismic deficiencies observed during our site visit and these have been documented in the report. Portable buildings pose several issues with regard to assessing their life safety hazards. First, drawings are often not available and when they are, it is not easy to associate specific drawings with specific portable buildings. Second, portable buildings are small one story wood or metal frame buildings and have demonstrated fairly safe performance in past earthquakes. Third, there is a likelihood that portable buildings (especially those constructed prior to 1982) are not in compliance with state regulations, either because they were not permitted or because the permit was for temporary occupancy and has expired.

Figures



Vista Hills Elementary School
2625 Barnard Street
Richmond, CA 94806
West Contra Costa Unified
School District
Site Acreage: 9.4

Figure 1: School Layout Plan



Figure 2: Front Entrance



Figure 3: Front Entrance



Figure 4: Courtyard



Figure 5: Courtyard



Figure 6: Portable Building



Figure 7: Rear View



Figure 8: Rear View



Figure 9: Interior



Figure 10: Glu-Lam Beam at Front