

West Contra Costa USD Lead Sampling Results

School Name	School ID	Location Type	Location Description	Sampled Date	Method	Parameter	Result (ug/L)	Qualifier	MDL	PQL
Cameron	327	Fountain	Df located to the left of the motor room to the right of the fire	2/16/2018	EPA-200.8	Lead	ND		0.1	1
Cameron	327	Tap	Tap located in Rm 2	2/16/2018	EPA-200.8	Lead	0.16	J	0.1	1
Cameron	327	Tap	Tap located in staff kitchen	2/16/2018	EPA-200.8	Lead	ND		0.1	1
Cameron	327	Tap	Tap located in staff office Rm	2/16/2018	EPA-200.8	Lead	1.7		0.1	1
Cameron	327	Tap	Tap located inside of Rm 5	2/16/2018	EPA-200.8	Lead	0.16	J	0.1	1
West County Mandarin	386	Tap	Tap located inside Rm 10	2/16/2018	EPA-200.8	Lead	1.4		0.1	1
West County Mandarin	386	Fountain	Closer Df located inside Rm 8	2/16/2018	EPA-200.8	Lead	1.5		0.1	1
West County Mandarin	386	Fountain	Closer Df located in Rm 5	2/16/2018	EPA-200.8	Lead	1.5		0.1	1
West County Mandarin	386	Tap	Tap located in Multipurpose Rm Kitchen	2/16/2018	EPA-200.8	Lead	1.3		0.1	1
West County Mandarin	386	Fountain	Df located in Rm 11	2/16/2018	EPA-200.8	Lead	0.1	J	0.1	1