

**Bayview Elementary Sample Results**

School Name	Location Type	Location Description	Sampled Date	Method	Parameter	Result (ug/L)	Qualifier	MDL	PQL
Bayview Elementary	Tap	Sink in admin building office near printer	12/6/2019	EPA-200.8	Lead	0.75	J	0.1	1
Bayview Elementary	Tap	Staff workroom in admin building	12/6/2019	EPA-200.8	Lead	0.62	J	0.1	1
Bayview Elementary	Tap	Left sink on back counter of room A6	12/6/2019	EPA-200.8	Lead	0.11	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room A5	12/6/2019	EPA-200.8	Lead	ND		0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room A4	12/6/2019	EPA-200.8	Lead	0.16	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room A2	12/6/2019	EPA-200.8	Lead	0.2	J	0.1	1
Bayview Elementary	Fountain	Upper fountain between A1 and A2	12/6/2019	EPA-200.8	Lead	0.39	J	0.1	1
Bayview Elementary	Tap	Hand washing sink in cafeteria kitchen	12/6/2019	EPA-200.8	Lead	0.48	J	0.1	1
Bayview Elementary	Fountain	Upper Df to the right of M4 inside near janitors closet	12/6/2019	EPA-200.8	Lead	1.2		0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room M4	12/6/2019	EPA-200.8	Lead	ND		0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink of leftmost sink in back corner of room M3	12/6/2019	EPA-200.8	Lead	0.66	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room M2	12/6/2019	EPA-200.8	Lead	0.35	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room M1	12/6/2019	EPA-200.8	Lead	0.9	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room C3	12/6/2019	EPA-200.8	Lead	0.35	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room C5	12/6/2019	EPA-200.8	Lead	0.14	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room C7	12/6/2019	EPA-200.8	Lead	0.18	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room C12	12/6/2019	EPA-200.8	Lead	0.21	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room C10	12/6/2019	EPA-200.8	Lead	0.22	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room C17	12/6/2019	EPA-200.8	Lead	0.54	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room C15	12/6/2019	EPA-200.8	Lead	0.27	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room C13	12/6/2019	EPA-200.8	Lead	0.42	J	0.1	1
Bayview Elementary	Fountain	Right df to the right of storage room and across from playground	12/6/2019	EPA-200.8	Lead	0.21	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room D18	12/6/2019	EPA-200.8	Lead	0.51	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room D25	12/6/2019	EPA-200.8	Lead	0.39	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room C20	12/6/2019	EPA-200.8	Lead	0.61	J	0.1	1
Bayview Elementary	Fountain	Fountain on right side of sink in room	12/6/2019	EPA-200.8	Lead	0.36	J	0.1	1
Bayview Elementary	Fountain	Right drinking fountain outside near D21	12/6/2019	EPA-200.8	Lead	0.2	J	0.1	1

**Bayview Elementary Sample Results**

School Name	Location Type	Location Description	Sampled Date	Method	Parameter	Result (ug/L)	Qualifier	MDL	PQL
Analytical Notes And Definitions:									
J = Estimated Value (CLP Flag)									
MDL = Method Detection Limit									
ND = Not Detected above the method detection limit									
PQL = Practical Quantitation Limit									