

Crespi Junior High Sample Results

School Name	Location Type	Location Description	Sampled Date	Method	Parameter	Result (ug/L)	Qualifier	MDL	PQL
Crespi Junior High	Tap	Tap in back corner of rm 201 next to handicap bathroom	11/20/2019	EPA-200.8	Lead	1.7		0.1	1
Crespi Junior High	Fountain	DF attached to right of 3 faucet sink in back of rm 101	11/20/2019	EPA-200.8	Lead	42		0.1	1
Crespi Junior High	Fountain	DF across from rm 209 on the corner	11/20/2019	EPA-200.8	Lead	5.5		0.1	1
Crespi Junior High	Tap	Tap at station 1 to the right of the door in rm 207	11/20/2019	EPA-200.8	Lead	6.1		0.1	1
Crespi Junior High	Fountain	Center DF (of 3) next to cafeteria doors	11/20/2019	EPA-200.8	Lead	0.23	J	0.1	1
Crespi Junior High	Tap	Small tap to right of three basin sink	11/20/2019	EPA-200.8	Lead	1.9		0.1	1
Crespi Junior High	Tap	Tap in room 422 (nurses office)	11/20/2019	EPA-200.8	Lead	ND		0.1	1
Crespi Junior High	Fountain	Lower DF by room 420	11/20/2019	EPA-200.8	Lead	9.1		0.1	1
Crespi Junior High	Fountain	Upper DF next to bathrooms next to room 201	11/20/2019	EPA-200.8	Lead	0.12	J	0.1	1
Crespi Junior High	Tap	Right tap in room 102	11/20/2019	EPA-200.8	Lead	16		0.1	1
Crespi Junior High	Fountain	DF in right sink in room 105	11/20/2019	EPA-200.8	Lead	7.2		0.1	1
Crespi Junior High	Tap	Tap on teachers island in room 206	11/20/2019	EPA-200.8	Lead	96		0.1	1
Crespi Junior High	Tap	Tap closest to door in room 204	11/20/2019	EPA-200.8	Lead	15		0.1	1
Crespi Junior High	Tap	Tap in room 406 (teachers lounge)	11/20/2019	EPA-200.8	Lead	0.50	J	0.1	1
Crespi Junior High	Fountain	Left DF between room 602 and 603	11/20/2019	EPA-200.8	Lead	5.7		0.1	1

Analytical Notes And Definitions:
J = Estimated Value (CLP Flag)
MDL = Method Detection Limit
ND = Not Detected above the method detection limit
PQL = Practical Quantitation Limit