

Montalvin Manor Elementary Sample Results

School Name	Location Type	Location Description	Sampled Date	Method	Parameter	Result (ug/L)	Qualifier	MDL	PQL
Montalvin Manor Elementary	Fountain	Fountain in room 106	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 104	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 102	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 101	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Tap	Food prep sink in community kitchen room 203 col	12/12/2019	EPA-200.8	Lead	0.89	J	0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 201	12/12/2019	EPA-200.8	Lead	0.12	J	0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 138	12/12/2019	EPA-200.8	Lead	0.38	J	0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 136	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 134	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in reading lab room 132	12/12/2019	EPA-200.8	Lead	0.13	J	0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 127	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Tap	Food prep sink in community kitchen cold water ta	12/12/2019	EPA-200.8	Lead	0.26	J	0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 125	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Tap	Cold tap in nurses office rm116	12/12/2019	EPA-200.8	Lead	1.6		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in rm 109	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in rm 108	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 107	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 105	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 103	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Upper fountain across room 155	12/12/2019	EPA-200.8	Lead	0.14	J	0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 202	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Upper fountain outside building between bathroom	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 139	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 137	12/12/2019	EPA-200.8	Lead	0.13	J	0.1	1
Montalvin Manor Elementary	Tap	Tap in room 135	12/12/2019	EPA-200.8	Lead	0.1	J	0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 133	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 131	12/12/2019	EPA-200.8	Lead	ND		0.1	1
Montalvin Manor Elementary	Fountain	Fountain in room 129	12/12/2019	EPA-200.8	Lead	0.77	J	0.1	1

Analytical Notes And Definitions:
J = Estimated Value (CLP Flag)
MDL = Method Detection Limit
ND = Not Detected above the method detection limit
PQL = Practical Quantitation Limit