

Sheldon Elementary Sample Results

School Name	Location Type	Location Description	Sampled Date	Method	Parameter	Result (ug/L)	Qualifier	MDL	PQL
Sheldon Elementary	Tap	Sink in nurses office	12/11/2019	EPA-200.8	Lead	0.11	J	0.10	1.0
Sheldon Elementary	Tap	Tap in teachers work room	12/11/2019	EPA-200.8	Lead	0.46	J	0.10	1.0
Sheldon Elementary	Tap	Sink in teachers lounge	12/11/2019	EPA-200.8	Lead	0.16	J	0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 25	12/11/2019	EPA-200.8	Lead	0.11	J	0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 19	12/11/2019	EPA-200.8	Lead	ND		0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 23	12/11/2019	EPA-200.8	Lead	ND		0.10	1.0
Sheldon Elementary	Tap	Step over in room 21, tap at back of room	12/11/2019	EPA-200.8	Lead	0.32	J	0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 12	12/11/2019	EPA-200.8	Lead	0.53	J	0.10	1.0
Sheldon Elementary	Tap	Tap on left side of sink in room 13	12/11/2019	EPA-200.8	Lead	0.72	J	0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 14	12/11/2019	EPA-200.8	Lead	0.26	J	0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 15	12/11/2019	EPA-200.8	Lead	0.27	J	0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 16	12/11/2019	EPA-200.8	Lead	0.16	J	0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 17	12/11/2019	EPA-200.8	Lead	ND		0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 18	12/11/2019	EPA-200.8	Lead	ND		0.10	1.0
Sheldon Elementary	Fountain	Upper fountain in hall near speech therapy, step ov	12/11/2019	EPA-200.8	Lead	0.14	J	0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 10	12/11/2019	EPA-200.8	Lead	ND		0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 11	12/11/2019	EPA-200.8	Lead	ND		0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 6	12/11/2019	EPA-200.8	Lead	ND		0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 7	12/11/2019	EPA-200.8	Lead	0.22	J	0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 8	12/11/2019	EPA-200.8	Lead	ND		0.10	1.0
Sheldon Elementary	Fountain	Upper fountain in corridor near room 8	12/11/2019	EPA-200.8	Lead	0.1	J	0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 1	12/11/2019	EPA-200.8	Lead	ND		0.10	1.0
Sheldon Elementary	Fountain	Upper DF between room 1 and 2	12/11/2019	EPA-200.8	Lead	ND		0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 4	12/11/2019	EPA-200.8	Lead	0.13	J	0.10	1.0
Sheldon Elementary	Fountain	Fountain on right side of sink in room 5	12/11/2019	EPA-200.8	Lead	0.22	J	0.10	1.0
Sheldon Elementary	Fountain	Lower fountain in multipurpose room	12/11/2019	EPA-200.8	Lead	0.13	J	0.10	1.0
Sheldon Elementary	Tap	Tap in office attached to kitchen	12/11/2019	EPA-200.8	Lead	1.9		0.10	1.0

Analytical Notes And Definitions:
J = Estimated Value (CLP Flag)
MDL = Method Detection Limit
ND = Not Detected above the method detection limit
PQL = Practical Quantitation Limit