

**Lovonya DeJean Middle School Sample Results**

School Name	Location Type	Location Description	Sampled Date	Method	Parameter	Result (ug/L)	Qualifier	MDL	PQL
Lovonya DeJean Middle School	Fountain	Upper DF in main admin hallway	11/19/2019	EPA-200.8	Lead	0.11	J	0.1	1
Lovonya DeJean Middle School	Tap	Tap in room A104 (workroom)	11/19/2019	EPA-200.8	Lead	0.32	J	0.1	1
Lovonya DeJean Middle School	Tap	Tap in classroom B104	11/19/2019	EPA-200.8	Lead	0.78	J	0.1	1
Lovonya DeJean Middle School	Tap	Tap in classroom B102	11/19/2019	EPA-200.8	Lead	0.15	J	0.1	1
Lovonya DeJean Middle School	Fountain	Lower DF upstairs in building B in between classrooms B201 and B203	11/19/2019	EPA-200.8	Lead	ND		0.1	1
Lovonya DeJean Middle School	Tap	Tap in room C104	11/19/2019	EPA-200.8	Lead	0.50	J	0.1	1
Lovonya DeJean Middle School	Tap	Tap in room C204	11/19/2019	EPA-200.8	Lead	0.53	J	0.1	1
Lovonya DeJean Middle School	Tap	Tap in workroom C207	11/19/2019	EPA-200.8	Lead	0.66	J	0.1	1
Lovonya DeJean Middle School	Tap	Tap in workroom D107	11/19/2019	EPA-200.8	Lead	1.8		0.1	1
Lovonya DeJean Middle School	Fountain	Lower DF in building D on 2nd floor in between classrooms D201 and D203	11/19/2019	EPA-200.8	Lead	0.11	J	0.1	1
Lovonya DeJean Middle School	Fountain	Upper DF on grass side of main admin building outside	11/19/2019	EPA-200.8	Lead	0.60	J	0.1	1
Lovonya DeJean Middle School	Fountain	Gym building lower DF across from classroom F101	11/19/2019	EPA-200.8	Lead	ND		0.1	1
Lovonya DeJean Middle School	Fountain	Upper DF in girls locker room	11/19/2019	EPA-200.8	Lead	0.32	J	0.1	1
Lovonya DeJean Middle School	Fountain	DF in classroom F104	11/19/2019	EPA-200.8	Lead	1.7		0.1	1
Lovonya DeJean Middle School	Tap	Tap in snack bar room G132	11/19/2019	EPA-200.8	Lead	8.5		0.1	1
Lovonya DeJean Middle School	Tap	Tap in NE corner on main kitchen area	11/19/2019	EPA-200.8	Lead	1.5		0.1	1
Lovonya DeJean Middle School	Fountain	DF in main Cafeteria area (not entry way)	11/19/2019	EPA-200.8	Lead	0.38	J	0.1	1
Lovonya DeJean Middle School	Fountain	DF in classroom G112	11/19/2019	EPA-200.8	Lead	0.27	J	0.1	1
Lovonya DeJean Middle School	Tap	Tap in rm A207 workroom	11/19/2019	EPA-200.8	Lead	0.61	J	0.1	1

Lovonya DeJean Middle School	Fountain	Upper df adjacent to stairs near rm B105 electric	11/19/2019	EPA-200.8	Lead	ND		0.1	1
Lovonya DeJean Middle School	Fountain	Df (upper) adjacent to stairs near c105 electric rm	11/19/2019	EPA-200.8	Lead	ND		0.1	1
Lovonya DeJean Middle School	Tap	Tap in rm adjacent to c105 electric	11/19/2019	EPA-200.8	Lead	0.50	J	0.1	1
Lovonya DeJean Middle School	Fountain	Upper df across across from c202 sci lab	11/19/2019	EPA-200.8	Lead	ND		0.1	1
Lovonya DeJean Middle School	Fountain	Upper Df adjacent to stairs and d105 electric rm	11/19/2019	EPA-200.8	Lead	ND		0.1	1
Lovonya DeJean Middle School	Tap	Tap in work rm d210	11/19/2019	EPA-200.8	Lead	0.95	J	0.1	1
Lovonya DeJean Middle School	Fountain	Df attached to tap in classrm f104	11/19/2019	EPA-200.8	Lead	1.1		0.1	1
Lovonya DeJean Middle School	Fountain	Df (upper) near hand driers in boys locker rm f109	11/19/2019	EPA-200.8	Lead	0.37	J	0.1	1
Lovonya DeJean Middle School	Fountain	Df lower next to f118 storage	11/19/2019	EPA-200.8	Lead	0.64	J	0.1	1
Lovonya DeJean Middle School	Tap	Tap in g133 staff lounge	11/19/2019	EPA-200.8	Lead	0.86	J	0.1	1
Lovonya DeJean Middle School	Tap	Food prep sink (left faucet of 3 basin sink) near g131 speedline	11/19/2019	EPA-200.8	Lead	1.4		0.1	1
Lovonya DeJean Middle School	Fountain	Df upper near exit and g120 girls restroom	11/19/2019	EPA-200.8	Lead	0.16	J	0.1	1
Lovonya DeJean Middle School	Fountain	Df upper between g104 men's restroom and g102 women's restroom	11/19/2019	EPA-200.8	Lead	0.22	J	0.1	1
Lovonya DeJean Middle School	Fountain	Df attached to sink next to g110 corridor	11/19/2019	EPA-200.8	Lead	0.81	J	0.1	1

<b>Analytical Notes And Definitions:</b>
J = Estimated Value (CLP Flag)
MDL = Method Detection Limit
ND = Not Detected above the method detection limit
PQL = Practical Quantitation Limit