

Murphy Elementary Sample Results

School Name	Location Type	Location Description	Sampled Date	Method	Parameter	Result (ug/L)	Qualifier	MDL	PQL
Murphy Elementary	Tap	Inside room 31 kitchenette in admin building	12/3/2019	EPA-200.8	Lead	0.31	J	0.1	1
Murphy Elementary	Tap	Sink in staff lounge	12/3/2019	EPA-200.8	Lead	0.18	J	0.1	1
Murphy Elementary	Tap	Sink inside preschool rm 39	12/3/2019	EPA-200.8	Lead	0.26	J	0.1	1
Murphy Elementary	Fountain	Upper fountain near door 11	12/3/2019	EPA-200.8	Lead	0.11	J	0.1	1
Murphy Elementary	Tap	Right side of three basin sink near exit door in kitchen	12/3/2019	EPA-200.8	Lead	0.92	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink inside classroom 11	12/3/2019	EPA-200.8	Lead	0.2	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 12	12/3/2019	EPA-200.8	Lead	0.19	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 13	12/3/2019	EPA-200.8	Lead	0.18	J	0.1	1
Murphy Elementary	Fountain	Lower fountain in corridor next to electrical panel room	12/3/2019	EPA-200.8	Lead	0.12	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of the sink in room 14	12/3/2019	EPA-200.8	Lead	0.81	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 15	12/3/2019	EPA-200.8	Lead	0.64	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 16	12/3/2019	EPA-200.8	Lead	1.5		0.1	1
Murphy Elementary	Fountain	Lower fountain outside central building area around the corner from room 16	12/3/2019	EPA-200.8	Lead	0.19	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 17	12/3/2019	EPA-200.8	Lead	1.8		0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 18	12/3/2019	EPA-200.8	Lead	1.3		0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 19	12/3/2019	EPA-200.8	Lead	0.45	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 9	12/3/2019	EPA-200.8	Lead	0.49	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 7	12/3/2019	EPA-200.8	Lead	0.18	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 6	12/3/2019	EPA-200.8	Lead	0.59	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 5	12/3/2019	EPA-200.8	Lead	0.46	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 4	12/3/2019	EPA-200.8	Lead	0.83	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 2	12/3/2019	EPA-200.8	Lead	0.62	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 2	12/3/2019	EPA-200.8	Lead	0.35	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room 1 (motor room)	12/3/2019	EPA-200.8	Lead	0.4	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink on right side of multi use room by library	12/3/2019	EPA-200.8	Lead	1.4		0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink on left side of multi use room near library	12/3/2019	EPA-200.8	Lead	0.59	J	0.1	1
Murphy Elementary	Tap	Sink inside library	12/3/2019	EPA-200.8	Lead	0.21	J	0.1	1
Murphy Elementary	Fountain	Upper water fountain across from library entrance	12/3/2019	EPA-200.8	Lead	0.15	J	0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room K22	12/3/2019	EPA-200.8	Lead	ND		0.1	1
Murphy Elementary	Fountain	Fountain on right side of sink in room K21	12/3/2019	EPA-200.8	Lead	0.3	J	0.1	1

Murphy Elementary Sample Results

School Name	Location Type	Location Description	Sampled Date	Method	Parameter	Result (ug/L)	Qualifier	MDL	PQL
Murphy Elementary	Fountain	Lower fountain on outside wall of k21	12/3/2019	EPA-200.8	Lead	0.22	J	0.1	1

Analytical Notes And Definitions:
J = Estimated Value (CLP Flag)
MDL = Method Detection Limit
ND = Not Detected above the method detection limit
PQL = Practical Quantitation Limit